

# Vehicle Safety Recall Quarterly Status Report

Required per 49 CFR Part 573.7

Report Date: October 29, 2009 Calendar Quarter: 3rd

Safety Recall Quarterly Report from July 1, 2009 through September 30, 2009

Manufacturer Name: American Suzuki Motor Corporation

Report Author: Ken Bush Phone: (714) 996-7040 ext. 2207

Recall Subject: 2005-06 VL800/VZ800 Ignition Switch

1. NHTSA Safety Recall Campaign Number: 05V-566

Suzuki Campaign Number: 2085

2. (a) The date notification to purchasers began: Initial owner notification letters were sent on January 6, 2006. Follow-up notification letters were sent on January 23, 2009.

(b) The date notification of purchasers was completed: January 23, 2009

3. The Total Number of Vehicles Involved: 23,839

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 15,244

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & Not Requiring Remedy: 0

Total number of vehicles involved in the recall and inspected, but determined to not require remedial or recall repair work.

5. Vehicles Determined to be Unreachable

Number Exported: 60

Number Stolen: 0

Number Scrapped: 0

Number of Undeliverable Notification Letters: 416 (Second Notification)

Number Otherwise Unreachable: 0

Describe Other: \_\_\_\_\_