

NHTSA Safety Recall Quarterly Report Information

Report Date: 4/18/03

Recall Quarterly Report from 1/01/03 through 3/31/03

Manufacturer: Coachmen Recreational Vehicle Company

Recall Number: #03V-040

Recall Subject: Ford Brake Warning Indicator

Total Items Involved: 3,539

Total Inspected and Remedied this Quarter: 12

Total Inspected and Remedied: 12

Total Unable to Notify: 0

Dealer Notification: March 1, 2003

Owner Notification: March 1, 2003

RECEIVED
NHTSA

APR 18 10 14 AM '03

APR 18 2003

Vehicle Safety Recall Quarterly Report Information

Required per 49 CFR Part 573.6

Report Date: Oct 1, 2002

Calendar Quarter: 3rdSafety Recall Quarterly Report from July 2002 through Sept 2002Manufacturer: Chance Coach, Inc.Report Author: Lonnie SkinkisRecall Subject: TRW Model 20-EDL Ball Socket1. NHTS Safety Recall Campaign Number: 00E-047

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SB-00003

2. (a) The date notification to purchasers began: October 5, 2000(b) The date notification of purchasers was completed: Still Open3. The total Number of Vehicles Involved: 84

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.

4. (a) Total Number Inspected & Remedied: 21

Total number of vehicles, which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 2

Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work

5. Vehicles Determined to be Unreachable

Total Number Exported: 0Total Number Stolen: 0Total Number Scrapped: 0Total Number Unable to Notify: 0Total Number Otherwise Unreachable: 0

Describe Other: _____

Vehicle Safety Recall Quarterly Report Informations

Required per 49 CFR Part 573.6

Report Date: Oct 1, 2002

Calendar Quarter: 3rdSafety Recall Quarterly Report from July 2002 through Sept 2002Manufacturer: Chance Coach, Inc.Report Author: Lonnie SkinkisRecall Subject: TRW Model 20-EDL Ball Socket1. NHTS Safety Recall Campaign Number: 02V-037.004

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: SB-103

2. (a) The date notification to purchasers began: August 15, 2002(b) The date notification of purchasers was completed: Still Open3. The total Number of Vehicles Involved: 33

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer.

4. (a) Total Number Inspected & Remedied: 1

Total number of vehicles, which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: 0

Total number of vehicles involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Vehicles Determined to be Unreachable

Total Number Exported: 0Total Number Stolen: 0Total Number Scrapped: 0Total Number Unable to Notify: 0Total Number Otherwise Unreachable: 0

Describe Other: _____