



ADMINISTRATIVE MESSAGE

03V-050

Message Author: Kathie Sherrill
Template Type: Standard
Author's Division/Department: Warranty Information
Status: Forwarded
Message Date: 05/27/2003
Message Number: WTR20030007

Message Criteria/Information

Dealer Recipient Criteria:	
Exclude BAC(s):	
Originating Dept:	
Subject:	SUBJECT: 03007 FRONT SAFETY BELT BUCKLES
Actionable Item:	Information Only
Actionable Item Details:	
Contact Person: (for Wholesale)	Name: Loren Rusk Phone: Email: Loren.Rusk/US/GM/GMC@GM Fax:
Contact Person: (for Wholesale)	Name: Phone: Email: Fax:
Contact Person: (for Dealership)	Name: Phone: Email: Fax:
Functional Role(s): (Recommended Distribution):	Parts Manager, Service Manager, Warranty Administrator

Message Categorization Information

Message Type:	Recalls
Revision Reference:	

Message Retention

Release Date:	05/27/2003
Archive Date:	08/28/2003

Dealer Solution: TO: ALL CHEVROLET AND GMC DEALERS
 ATTN: PARTS MANAGER, SERVICE MANAGER, AND WARRANTY ADMINISTRATOR

GM SERVICE AND PARTS OPERATIONS
 DCS1051
 URGENT - DISTRIBUTE IMMEDIATELY

DATE: May 27, 2003

SUBJECT: 03007 FRONT SAFETY BELT BUCKLES

MODELS: 2003 CHEVROLET EXPRESS
 2003 GMC SAVANA
 WITH GVW LESS THAN 8500 LBS. (3856 KG)

TO: ALL CHEVROLET AND GMC DEALERS

ATTN: PARTS MANAGER, SERVICE MANAGER, AND WARRANTY

ADMINISTRATOR

General Motors is announcing Product Safety Recall 03007 today. See the attached bulletin for details.

MAILING INFORMATION

Dealer bulletin mailing will begin May 27, 2003.

Owner letter mailing will begin June 3, 2003.

GM Vehicle Inquiry System (GMVIS)

GMVIS Information will be available on May 28, 2003.



03007 Bulletin.pdf

END OF MESSAGE

GM SERVICE AND PARTS OPERATIONS

VSSM Library Fields

|) Do Not Send Message to VSSM Library



Service Parts Operations

RPB#

DISTRIBUTION:

- | | |
|---|--|
| <input type="checkbox"/> DEALER PRINCIPAL | <input type="checkbox"/> USED CAR SALES |
| <input type="checkbox"/> PARTS MANAGER | <input type="checkbox"/> BODY SHOP MANAGER |
| <input type="checkbox"/> SERVICE MANAGER | <input type="checkbox"/> BUSINESS/GENERAL |
| <input type="checkbox"/> NEW CAR SALES | <input type="checkbox"/> OTHER |

PLEASE INITIAL AND RETURN TO PARTS MANAGER FOR PERMANENT FILE

Recall Parts Bulletin

TO: CHEVROLET AND GMC DEALERS

DATE: MAY 27, 2003

FROM: J. M. STONE, RECALL MANAGER

03V-050

SUBJECT: 03007 - FRONT SAFETY BELT BUCKLES

ATTN: PARTS MANAGER

PRODUCT SAFETY RECALL # 03007 - MAY 27, 2003

DESCRIPTION:

- General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2003 model year Chevrolet Express and GMC Savana vehicles with a GVW less than 8500 pounds (3856 kg). During a vehicle crash of sufficient severity to deploy the safety belt pretensioner, the front safety belt buckles in some of these vehicles may not release after the vehicle crash, or alternately may eject the front safety belt latches during the vehicle crash, resulting in increased risk of personal injury.
- Dealers are to replace the front driver and passenger side safety belt buckles.
- Refer to Product Safety Recall Bulletin for further information.

EFFECTIVE DATE:

- Initial owner mailing is scheduled to begin: **June 3, 2003.**

GENERAL INFORMATION:

Part Number	Description	Quantity/Vehicle
88955899	Belt Kit, D/Seat (Bkl Si) (Pewter)	1
88955897	Belt Kit, P/Seat (Bkl Si) (Pewter)	1
88955900	Belt Kit, D/Seat (Bkl Si) (Neutral)	1
88955898	Belt Kit, P/ Seat (Bkl Si) (Neutral)	1