

Equipment Safety Recall Quarterly Report Information¹

Required per 49 CFR Part 573.6

Report Date: July 19, 2001 Calendar Quarter: 1st July report, 2nd Calendar ¼ of 2001

Safety Recall Quarterly Report from April 1, 2001 through June 30, 2001

Manufacturer: Chalmers Suspensions International Inc.

Report Author: Steve Clarke Phone: (906) 624-9750

Recall Subject: Fixed Fabricated torque Rods

1. NHTSA Safety Recall Campaign Number: 01E021

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: N/A

2. (a) The date notification to purchasers began: May 2, 2001 to all OEM's involved

(b) The date notification of purchasers was completed: May 2, 2001 to the OEM's. Notification to the end user/ owner has not in all OEM's cases been completed. International, Mack, Volvo was completed by the end of June. The balance is still pending.

3. The Total Number of Items of Equipment Involved: 670 trucks total. That have a total of 2,179 torque rod that may be defective, that are to be replaced.

The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 27

Total number of items which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A, all trucks (670) must have the part (fixed fabricated torque rod) replaced.

Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work.

5. Items Determined to be Unreachable

Total Number Exported: To date 27 (this will change as more OEM report)

Total Number Stolen: Do not have this information

Total Number Scrapped: N/A

¹Any questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-6227 or by FAX at (202) 366-7882.

Total Number Unable to Notify: Do not have this information until all OEM's report

Total Number Otherwise Unreachable: Do not have this information until all OEM's report

Describe Other:

Equipment Safety Recall Quarterly Report Information¹

Required per 49 CFR Part 573.6

Report Date: February 22, 2002

Calendar Quarter: 3rd qly report
4th quarter 2001

Safety Recall Quarterly Report from April 1, 01 through Dec. 31, 01

Manufacturer: Chalmers Suspensions International Inc.

Report Author: Steve Clarke

Phone: (905) 624-9750

Recall Subject: Fixed Fabricated Torque Rods

1. NHTSA Safety Recall Campaign Number: 018021

Also, for completeness, if your company has assigned a code number to this campaign, please provide your code: N/A

2. (a) The date notification to purchasers began: May 2, 2001 to all OEM's involved

(b) The date notification of purchasers was completed: May 2, 2001 to all OEM's, Notification to truck owners is to be completed by OEM's.

3. The Total Number of Items of Equipment Involved: 670 trucks total that have 2,179 torque rod
The total number of items involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

Number of Items Returned from Inventory or Remedied Prior to Sale: 0

Includes (a) the total number of items returned from Manufacturer, Distributor, Dealer or Retailer inventory or (b) otherwise remedied prior to sale to consumers.

4. (a) Total Number Inspected & Remedied: 335 kits have shipped for 335 trucks. We presume
Total number of items which were inspected and/or otherwise repaired or remedied. 100% of these have been remedied.

(b) Total Number Inspected & NOT REQUIRING REMEDY: N/A all trucks (670) must have
Total number of items involved in the recall and inspected, but determined to NOT REQUIRE REMEDIAL or recall repair work. these torque rods replaced.

5. Items Determined to be Unreachable

Total Number Exported: To date 27 (this may change based on OEM reports).

Total Number Stolen: N/A

Total Number Scrapped: N/A

Total Number Unable to Notify: Do not have this information until OEM's report.

Total Number Otherwise Unreachable: Do not have this information until OEM's report.

Describe Other: N/A

¹Any questions please contact Mrs. Kelly Schuler or Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.