

Vehicle Safety Recall Quarterly Status Report

Required per 49 CFR Part 573.7

Report Date: July 26, 2012 **Calendar Quarter:** Second

Safety Recall Quarterly Report from April 1, 2012 **through** June 30, 2012

Manufacturer Name: American Suzuki Motor Corporation

Report Author: Wayne Powell **Phone:** (714) 996-7040 Ext. 2046

Recall Subject: Replacement of Sidestand Switch Bolts on Model Year 2009 thru 2011 GSX-R1000 Motorcycles

1. NHTSA Safety Recall Campaign Number: 12V-231

Suzuki Campaign Number: 2A29

2. (a) The date notification to purchasers began: June 7, 2012

(b) The date notification of purchasers was completed: June 7, 2012

3. The Total Number of Vehicles Involved: 4,969

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 533

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & Not Requiring Remedy: 0

Total number of vehicles involved in the recall and inspected, but determined to not require remedial or recall repair work.

5. Vehicles Determined to be Unreachable

Number Exported: 0

Number Stolen: 6

Number Scrapped: 7

Number of Undeliverable Notification Letters: 0

Number Otherwise Unreachable: 0

Describe Other: _____