



MAZDA DEALER EMAIL

zoom-zoom

zoom-zoom

zoom-zoom

November 13, 2013

Attention: Mazda Parts & Service Managers

Subject: Safety Recall 6812G – 2006-2008 MY Revised Parts Are Available

Revised 6812G recall parts are now available for affected mid-2006 - 2008 model year Tributes. An initial order of p/n 1F03-10-218 rear stud with spacer assemblies, based on a percentage of dealer sales, should arrive at your dealership no later than November 19, 2012. You will soon receive a separate communication with details on this initial parts order.

For 2006 model year vehicles, inspect the engine cover (see inspection step in the 6812G repair procedure) to determine the required part.

Notifications will be mailed on November 15 to affected 2006 and 2008 model year owners.

IMPORTANT

To prevent possible subsequent vehicle damage, dealers must install only the engine cover rear stud with spacer assembly intended for the model year vehicle under repair. Any damage caused by installing the incorrect part will not be covered by warranty.

- Install p/n 1F01-10-218 ONLY on affected 2001-2005 and early 2006 model year Tributes.
- Install p/n 1F03-10-218 ONLY on affected mid-2006 – 2008 model year Tributes.

For technical assistance, contact the Technical Assistance Hotline at (888) 832-8477, Option 3 for English speaking Hotline Specialist, Option 4 for Spanish speaking Hotline Specialist.

For warranty questions, contact the Warranty Hotline at (877) 727-6626, Option 3.

For parts order questions, contact the Dealer Assistance Group at (877) 727-6626, Option 2.

Our apologies for any inconvenience to your dealership and your customers. Thank you for your support in carrying out this campaign.

Mazda Technical Services