



**RECEIVED**  
By Recall Management Division at 8:51 am, Dec 19, 2012

Bombardier Recreational Products Inc.  
726 Saint-Joseph Street  
Valcourt, Québec, Canada J0E 2L0

www.brp.com

12V-581  
(2 pages) Amended

December 14, 2012

By email only

Ms. Kelly Schuler  
Safety Recall Specialist  
Recall Management Division  
Office of Defect Investigation  
Enforcement  
National Highway Traffic Safety Administration  
1200 New Jersey Avenue SE., W45-306  
Washington, DC 20590

**Re: Amendments to Defect Information Report Pursuant to 49 CFR Part 573 – Fuel Vapor Canister Vent Hose Inspection/Replacement**

Dear Ms. Schuler:

As mentioned, please find our amendments from our initial report dates December 11, 2012.

• **AMENDED 573.6 (c) (2) Identification of the Vehicles involved in the Recall:**

YEAR	MODEL	MODEL NUMBER
2008	Spyder™ GS SM5 and SE5	All
2009	Spyder GS SM5 and SE5	All
2010	Spyder RS SM5 and SE5	All

The serial number list will be enclosed in the final Safety Recall Bulletin.

• **AMENDED 573.6 (c) (3) Number of Vehicles Potentially Affected:**

Approximately 9600.

• **AMENDED 573.6 (c) (8) Program for Remedy of Defect:**

We are sending new version of Dealer letter and Bulletin due to the addition of some MY 2010. Please note that the bulletin number changed as well due to our numbering system which uses the more recent model year involved in a campaign.

Ski-Doo  
Lynx  
Sea-Doo  
Evinrude  
Johnson  
Rotax  
Can-Am

If you have any questions regarding this report, please contact the undersigned.

Sincerely yours,



BRP US Inc and Bombardier Recreational Products Inc.  
Marie-Claude Simard  
Manager, Product Safety  
Legal Department  
T. 450-532-6195  
[marie-claude.simard@brp.com](mailto:marie-claude.simard@brp.com)

Enclosures