

From: [Broadcast Messaging System](#)
To: [DL-BMS Message Monitors](#)
Subject: E70 Brake Booster Vacuum Line Recall
Date: Thursday, February 07, 2013 5:07:35 PM

Publish Date: February 07, 2013
From: Technical Service
Expiration Date: February 21, 2013

DCSnet Message 
Important

Subject: **E70 Brake Booster Vacuum Line Recall**

To: BMW Service Managers, BMW Service Advisors,

BMW is conducting a voluntary safety Recall on certain model year 2007-2010 E70 vehicles equipped with the N62T engine.

It is possible for engine oil to enter the brake vacuum line and, in rare cases, contaminate the brake booster. Vehicles will have the vacuum line checked for the presence of oil and have the vacuum line replaced. If oil is found in the vacuum line, the brake booster and master cylinder will also be replaced.

Customers will receive a Recall letter by the end of February, asking them to schedule a center visit for the repair. A Service Information bulletin and DCS message concerning parts ordering will be published next week.

Attached is a list of Questions and Answers which should address most inquiries customers may have. Please provide and discuss this information with your staff.

Sincerely,

Technical Service

Attachments:  [2013-E70--BrakeVacuumPump_QA_4 \[80f980d3\].pdf](#)  [2013-E70--BrakeVacuumPump_QA_4 \[80f980d3\].pdf](#)

Recipients: BMW SAV (Light Trucks), All Offerings, All Regions, All Areas, Service, All
BMW Passenger Cars, All Offerings, All Regions, All Areas, Service, All