

[Next Unread Message](#)**View Message**

Sent on 03 14 2013 **Expires on** 03 28 2013
From American Honda Parts & Service Division, Campaign Administration
Subject Stop Sale/Safety Recall: 2005 Pilot VSA Malfunction

DATE: March 14, 2013

TO: All Honda Sales, Service & Parts Managers and Personnel

FROM: American Honda Parts & Service Division, Campaign Administration

RE: Stop Sale/Safety Recall: 2005 Pilot VSA Malfunction

Today, March 14, 2013, American Honda will notify NHTSA of a **Stop Sale** order and **Safety Recall** for some 2005 Pilot units. Any used units in dealer stock must be repaired per S/B 13-026: *Safety Recall: VSA System Unexpectedly Activates* prior to sale. **Refer to VIN Inquiry to determine which units in your inventory are affected.** American Honda Motor Co. expects to begin customer notification in mid-April 2013.

Note: Affected vehicles should not be sold until the repair has been performed. Should an unrepaired vehicle cause any injury or damage because of the required recall repair, the dealership will be solely responsible to the damaged party, and will be required to defend and indemnify American Honda for any resulting claims.

Basic Problem

A malfunction in the VSA system may cause the brake assist feature to activate unexpectedly.

Campaign Information

All affected vehicles require repair of the VSA control unit connector; some vehicles will also require inspection of the G302 ground clamp bolt. Please refer to iN VIN status inquiry to determine which repair applies to a particular vehicle.

Parts Information

Parts to support this recall including harness repair kits and tools will be available for order as of March 16, 2013.

Warranty and Repair Information

Warranty and repair information will be detailed in S/B 13-026, which will be posted to ISIS on March 16, 2013.

[Click here](#) for additional details.

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.