

[Next Unread Message](#)**View Message**

Sent on 04 12 2013 **Expires on** 04 25 2013
From American Honda Parts, Service & Technical Division, Campaign Administration
Subject Stop Sale/Safety Recall: 2012-13 CRV & Odyssey A/T Shift Lever

DATE: April 12, 2013

TO: All Honda Sales, Service & Parts Managers and Personnel
FROM: American Honda Parts, Service & Technical Division, Campaign Administration

RE: Stop Sale/Safety Recall: 2012-13 CR-V & Odyssey A/T Shift Lever

Today, April 12, 2013, American Honda will notify NHTSA of a **Stop Sale** order and **Safety Recall** for some 2012-13 CR-V and Odyssey units. Any used units in dealer stock must be repaired per S/B 13-035: *Safety Recall: 2012-13 CR-V Shift Interlock Stopper* or S/B 13-036: *Safety Recall: 2012-13 Odyssey Shift Interlock Stopper* prior to sale. **Refer to VIN Inquiry to determine which units in your inventory are affected.** American Honda Motor Co. expects to begin customer notification in mid May 2013.

Note: Affected vehicles should not be sold until the repair has been performed. Should an unrepaired vehicle cause any injury or damage because of the required recall repair, the dealership will be solely responsible to the damaged party, and will be required to defend and indemnify American Honda for any resulting claims.

Basic Problem

The shift interlock stopper, which is located in the A/T shift lever assembly, was manufactured out of specification. In sub-freezing conditions, it may be possible to move the shift lever out of P without pressing the brake pedal.

Campaign Information

All affected vehicles require replacement of the shift lock stopper with a countermeasured part.

Parts Information

A number of shift lock stopper sets have been distributed to all dealerships via FedEx, and are expected to arrive today, April 12, 2013. Note that these parts are intended to address your stop sale units. American Honda will notify all dealers via iN message when parts are made available for order.

Warranty and Repair Information

Warranty and repair information are detailed in the preliminary versions of S/Bs 13-035 and 13-036, which were posted on ISIS April 12, 2013.

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.