



July 2013

**VEHICLE SAFETY DEFECT SERVICE BULLETIN**  
**Recall Campaign 13V284000 US Units**  
**Recall Campaign 2013-225 CA Units**  
**Monaco Campaign 13001MRV**

**Re: Safety Recall – Water Tank Mounting System**

Dear Monaco RV, LLC Dealer:

Monaco RV, LLC has decided that a defect which relates to motor vehicle safety exists in certain vehicles built by Monaco RV. The affected vehicles are certain **Discover Canada RV** 2012 Cobalt Trail Expedition, 2011 Cobalt Trail TC, 2011 Cobalt Trail TL, 2012 Cobalt Trail TS UltraLite, and 2012 Cobalt Trail XLT UltraLite; **Holiday Rambler** 2012-2014 Aluma-Lite, 2012-2014 Aluma-Lite Ultra, and 2011 Campmaster; **McKenzie** 2013-2014 Rainier Ascent; **R-Vision** 2011-2012 Onyx, 2011 Trail Cruiser, 2013-2014 Trail Lite Trek, 2011-2013 Trail Lite, 2012-2014 Trail Sport, and 2012-2014 Trail-Lite Crossover.

The affected travel trailers were manufactured from October 12, 2009 through May 15, 2013 with water tanks mounted under the floor within enclosed underbellies.

A copy of the notification letter that is being sent to owners is enclosed.

The National Traffic and Motor Vehicle Safety Act provides that each vehicle subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. Generally, failure to repair within sixty (60) days after the owner's first delivery for repair is assumed to be an unreasonable delay. In the owner letter, customers are instructed to contact Monaco RV, LLC Customer Service (877-466-6226) or the Recall Hotline (800-685-6545) if on the agreed service date or within 3 days of the agreed date the dealer does not remedy the condition.

**THE ISSUE**

The fresh water tank mounting system may fail.

**AFFECTED UNITS**

If our records indicate that you have any of the affected vehicles in your inventory, you will also receive an owner notification letter identifying those units. *Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.*

**THE REPAIR**

The remedy will involve installing a cross brace between the fresh water tank mounting brackets. Please review the repair instructions for the labor operation code and labor time allowance. If you have any questions concerning the repair procedure, please contact a member of our Technical Support staff toll free at 1-877-466-6226.

The vehicle owner is responsible for having this service action performed. Monaco RV, LLC specifically excludes coverage of incidental damages that may result from failure to have this recall performed. Please have this recall performed as soon as possible.

**DEALER CAMPAIGN RESPONSIBILITY**

All unsold new/used vehicles in dealer's possession and subject to this campaign must be held and inspected/repaired per the service procedure of this campaign bulletin before owners take possession of these vehicles. Dealers are to service all vehicles subject to this campaign at no charge to owners, regardless of mileage, age of vehicle, or ownership, from this time forward.

Owners of vehicles recently sold from your new/used vehicle inventory for which the dealer receives the owner recall notification are to be contacted by the dealer, and arrangements made to make the required correction according to the instructions enclosed with this bulletin. This could be done by mailing to such owners a copy of the applicable owner letter accompanying this bulletin. Please also notify Monaco RV of any such owner for whom you have received notification.

In the future, whenever any vehicle subject to this campaign enters your vehicle inventory, or is in your dealership for service, for any reason, please make sure the campaign correction has been made *before* selling or releasing the vehicle.

Thank you for your support!

Sincerely,

A handwritten signature in black ink, appearing to read "Angela Brooks", written in a cursive style.

Angela Brooks  
Recall Administrator