



Aftersales Retailer Support

1996-2004 Pathfinder Front Strut Housing Corrosion Voluntary Safety Recall Campaign & Service Campaign

Reference: R1109 & R1110

Date: December 3, 2013

**Attention: Retailer Principal, Sales, Parts and
Service Managers**

Bulletin Information:

Infiniti has updated the campaign bulletins for the 1997-2003 QX4 Front Strut Housing Corrosion Recall Campaign (R1109) and Service Campaign (R1110). The bulletin changes taking effect are the following:

- The inspection area that determines if vehicle is repairable has been reduced in size.
- If the metal in the area one (1) repair area will not support rivet nuts, continue with the repair.
- Rivet nuts in repair area one (1) are preferred but not required in these holes.

Morley, our third-party company responsible for inspecting non-repairable vehicles, will be trained on the new inspection procedure. Please discard all previous versions of this bulletin.