

Audi of America, Inc.



Date: December 17, 2013

To: Audi Dealer Principal, Service Manager, and Parts Manager

From: Audi Product Compliance

Subject: Revision to Voluntary Safety Recall 20U6
Fuel Line

Dear Audi Dealer Principal, Service Manager, and Parts Manager:

This is to inform you of a revision to the Safety Recall 20U6 repair procedure. The repair procedure has been updated to eliminate the air filter housing removal, and as a result the time units to perform this recall have been adjusted.

- Please ensure all technicians review the updated procedure published on Elsa and ServiceNet.
- Please ensure all printed copies are destroyed and no longer available.

Audi Product Compliance

Audi of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326
+1 248 754 5000
www.audiusa.com