



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

December 27, 2013

Mr. Nasser Zamani
Daimler Trucks North America
4747 N. Channel Avenue
PO Box 3849
Portland, OR 97217-3849

NVS-215KS
13V-605

Subject: Left Outer Tie Rod may Fracture

Dear Mr. Zamani:

This letter serves to acknowledge Daimler Trucks North America's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

STERLING/BULLET/2008-2009

Mfr's Report Date: November 25, 2013

NHTSA Campaign Number: 13V-605

Components:

STEERING:LINKAGES:TIE ROD ASSEMBLY

Potential Number of Units Affected: 2,564

Problem Description:

Daimler Trucks North America (DTNA) is recalling certain model year 2008-2009 Sterling Bullet trucks manufactured October 15, 2007, through November 10, 2008. In the affected vehicles, the left outer tie rod ball stud may fracture.

Consequence:

A failure of the tie rod assembly may result in a loss of steering control, increasing the risk of a crash.

Remedy:

DTNA will notify owners, and dealers will replace the tie rod assembly with a redesigned assembly, free of charge. The recall is expected to begin by January 24, 2014. Customers may contact DTNA at 1-800-547-0712. DTNA's number for this recall is FL-655.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

On August 20, 2013, NHTSA announced new changes to the requirements governing safety recalls. Some of these requirements are already in effect. Please ensure your company will be in compliance with each requirement on, or before, its respective effective date. For a summary of the requirements and their effective dates please click on the "New!" link at <http://www.safercar.gov/Vehicle+Manufacturers>.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement