

[Next Unread Message](#)**View Message**

**Sent on** 09 27 2013 **Expires on** 10 11 2013  
**From** Parts Operations  
**Subject** STOP SALE and SPECIAL DEALER RETURN- 2007-08 Fit Power Window Master

If you have the following Power Window Master Switch Seals in your inventory, immediately stop selling and return them back to American Honda. A new Master Switch (P/N: 35756-SAA-406) which includes the seal is available as replacement.

Refer to Service Bulletin A13-052 *Safety Recall: 2007-08 Fit Power Window Master Switch May Not Work* for warranty and repair information.

Parts Return Procedure for Dealer Inventory ONLY:

Affected P/Ns: 35751-SAA-305, 35751-SAA-306 and 35751-SAA-307

- Complete the iN OAR Procedure.
- Use Reason Code "R" with eleven zeros for the shipper number.
- Use item number "9999".
- Enter "Fit Power Window Master Switch Seal Return" in the Remarks Section.
- After approved, an "Authorized Return document" will be received by mail.
- Send part/s back as normal with the "Return Authorization" attached via your returning DSA Truck or normal method of return.
- Deadline for this Special Return is **10/15/13**.

Thank you,

American Honda Motor Co., Inc.  
Parts Operations

NG/ms

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.