

View Message

Sent on 02 02 2013 Expires on 02 15 2013
 From Parts Division
 Subject 2003-04 Odyssey & Pilot Shift Interlock- Part Availability and Part Return

Basic Problem

On September 27, 2012, American Honda announced a stop sale and safety recall for all 2003-04 Odyssey & Pilot models due to potential shift interlock lever failure. When the campaign was launched, countermeasure parts were not available for order.

Effective immediately, the below countermeasured campaign kits are available for order. All warranty repairs using the new kit should be filed as campaign repairs as listed on S/B 13-011.

Campaign Type:	Safety Recall	
Service Bulletin:	13-011	
Affected Vehicles:	All 2003-04 Odyssey and Pilots	
Part Information		
Description	P/N	Application
KIT, LEVER (A)	06351-S84-000	Used for all campaign repairs
KIT,CYLINDER	06352-S9V-A01	Used only if key can be removed when shift lever is not in Park

Key Cylinder Sets and Steering Lock Assemblies mentioned below have been discontinued. A notification will be made at a later date when countermeasured Key Cylinder Sets and Steering Lock Assemblies become available.

Model	Part Description	Part Number	Action
Odyssey	CYLINDER SET, KEY	06350-S0X-A32ZANI	Stop Selling Immediately and return via OAR R
	CYLINDER SET, KEY	06350-S0X-A42ZANI	
	CYLINDER SET, KEY	06350-S0X-A42ZBNI	
	CYLINDER SET, KEY	06350-S0X-A42ZCNI	
	CYLINDER SET, KEY	06350-S0X-A52ZANI	
	CYLINDER SET, KEY	06350-S0X-A52ZBNI	
	CYLINDER SET, KEY	06350-S0X-A52ZCNI	
	LOCK ASSY, STEERING	35100-S0X-305NI	
PILOT	CYLINDER SET, KEY	06350-S9V-A02ZANI	Stop Selling Immediately and return via OAR R
	CYLINDER SET, KEY	06350-S9V-A02ZBNI	
	CYLINDER SET, KEY	06350-S9V-A02ZCNI	
	CYLINDER SET, KEY	06350-S9V-A12ZANI	
	CYLINDER SET, KEY	06350-S9V-A12ZBNI	
	CYLINDER SET, KEY	06350-S9V-A12ZCNI	
	LOCK ASSY, STEERING	35100-S9V-309NI	
	CYLINDER SET, KEY	06350-S9V-Y01ZCNI	

Immediately suspend all sales of pre countermeasured Key Cylinder Sets and Steering Lock Assemblies currently in your inventory. All parts must be returned back to American Honda.

Return Offer

You must return all parts listed above that you have in inventory.

No Shipment Listing or Invoice is required for this return. These returns will not be charged against your SRA credit.

Return in OAR Procedure

1. Complete the in OAR procedures.
2. Use Reason Code "R," with eleven zeros for the Shipper Number.
3. Use Item Number "9999."

INTERACTIVE NETWORK

4. Enter "Ignition Switch Return" in the Remarks Section.
5. When approved an "Authorization Return document" via the mail will be received. Please return parts as normal with the "Return Authorization attached."
6. Return ignition switches on your returning DSO Truck or normal method of return.
After receiving the Authorized Return Documents, ship the parts freight prepaid.
You will be credited return freight charges. Order adjustment requests (OARs) must be submitted by 02/28/13.

Thank you,

American Honda Motor Co., Inc.
Parts Operations

NG/ms

© 2000–2013, American Honda Motor Co., Inc. All Rights Reserved.