



Michael A. Berardi  
Director  
Service Engineering Operations  
Ford Customer Service Division

Ford Motor Company  
P. O. Box 1904  
Dearborn, Michigan 48121

July 1, 2014

**TO:** All U.S. Ford and Lincoln Dealers

**SUBJECT: DEMONSTRATION / DELIVERY HOLD Advance Notice - Safety Recall 14S11**  
Certain 2011-2014 Model Year F59 Commercial Chassis Vehicles  
Battery Cable Junction Block Replacement

**AFFECTED VEHICLES**

Certain 2011-2014 model year F59 Commercial Chassis vehicles built at the Detroit Chassis Plant from Job #1 2011 through April 30, 2014. Affected vehicles are identified in OASIS. In addition, for a list of vehicles assigned to your dealership, visit <https://web.fsavinlists.dealerconnection.com>. This information will be available on July 1, 2014

**REASON FOR THIS SAFETY RECALL**

Affected vehicles may develop a conductive path to ground between the battery cable junction block and the vehicle frame. This condition can result in a short circuit to ground, potentially leading to smoke, loss of electrical power, or fire with or without the engine running.

**SERVICE ACTION**

DO NOT DEMONSTRATE OR DELIVER any of the affected vehicles involved in this safety recall. A complete Dealer Bulletin will be provided to dealers by the week of July 21, 2014 when it is anticipated that parts ordering information and repair instructions will be available to support this safety recall.

**CUSTOMER NOTIFICATION**

Owners of record will be notified via first-class mail after repair instructions and parts ordering information have been provided to dealers.

**PLEASE NOTE:**

**Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$7,000 per vehicle. Correct all vehicles in your new vehicle inventory prior to delivery**

**QUESTIONS?**

Special Service Support Center (Dealer Assistance Only) .....1-800-325-5621

Sincerely,

Michael A. Berardi