



08/06/2014

New Safety Recall Advanced Communication – P43080614

Chrysler Group LLC (Chrysler) announced a safety recall on certain 2015 model year (UF) Chrysler 200 model vehicles equipped with sales code JPD.

A small number of the above vehicles were built with the incorrect gauge electrical wire in the driver's side front door wiring harness. As a result, the driver's front door window may become inoperative and/or the electrical circuit(s) may overload and produce excessive heat during use. Excessive heat may melt the electrical wire insulation and cause a short circuit with adjacent wires. This condition could cause a loss of other driver's side front door functions and/or an electrical fire without warning.

Chrysler will conduct a voluntary safety recall on all involved vehicles to replace the driver's door electrical wire harness.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
Chrysler Group LLC