



09/04/2014

New Safety Recall Advanced Communication – P54090414

Chrysler Group LLC (Chrysler) announced a safety recall on all 2011 model year (WD/WK) Dodge Durango and Jeep Grand Cherokee equipped with a 3.6L or 5.7L engine.

Some of the above vehicles may experience a failure in the electric fuel pump relay located within the Totally Integrated Power Module-7 (TIPM-7). A vehicle with a failed fuel pump relay may intermittently or permanently:

- not start.
- not start on the first attempt.
- not stay running upon startup.
- cause the engine to stall while driving.
- cause the electric fuel pump to remain energized after vehicle shutdown.

Chrysler will conduct a voluntary safety recall on all involved vehicles to install a standalone external electric fuel pump relay.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations
Chrysler Group LLC