



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

September 22, 2014

Mr. Dan Allen
Chief Engineer of Mfg. and Service Support
NABI Bus, LLC
106 National Drive
Anniston, AL 36207

NVS-215KS
14V-508

Subject: Fuel Filter Shell may Separate and Cause Stall

Dear Mr. Allen:

This letter serves to acknowledge NABI Bus, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

NABI/BRT/2014
NABI/LFW/2014

Mfr's Report Date: August 18, 2014

NHTSA Campaign Number: 14V-508

Components:

FUEL SYSTEM, DIESEL

Potential Number of Units Affected: 35

Problem Description:

NABI Bus, LLC (NABI) is recalling certain model year 2014 LFW and BRT transit buses manufactured May 2, 2014, to August 8, 2014. The Cummins ISB or ISL engines in these vehicles may have been equipped with Fleetguard UFF-XT fuel filters, part number FF63009, whose filter shell may separate from the fuel filter nut plate causing the engine to stall without warning.

Consequence:

If the engine stalls unexpectedly, there is an increased risk of a crash.

Remedy:

NABI will work with Cummins to notify owners, and Cummins service centers will install a new fuel filter, free of charge. The recall began in September 2014. Owners may contact NABI customer service at 1-256-831-4296 or Cummins customer service at 1-800-223-4583. NABI's number for this recall is 20144.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

We understand that Cummins will be handling the quarterly reporting for this campaign. Please be reminded that as the vehicle manufacturer, NABI is ultimately responsible for conducting an adequate safety recall campaign of its vehicles. Accordingly, if this safety recall campaign is not successful, the agency may require NABI to conduct a follow-up notification and conduct additional quarterly reporting.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a long horizontal stroke at the end.

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement