



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

September 24, 2014

Mr. Yoshio Coy  
Director of Product Support  
Agility Fuel Systems  
1815 E. Carnegie Avenue  
Santa Ana, CA 92705

NVS-215MR  
14E-056

**Subject:** Corrosion of Fuel Hoses may Result in CNG Leak

Dear Mr. Coy:

This letter serves to acknowledge Agility Fuel Systems's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

AGILITY/SIDE-MOUNT CNG FUEL/9999

**Mfr's Report Date:** August 22, 2014

**NHTSA Campaign Number:** 14E-056

**Components:**

FUEL SYSTEM, OTHER:DELIVERY:HOSES, LINES/PIPING, AND FITTINGS

**Potential Number of Units Affected:** 99

**Problem Description:**

Agility Fuel Systems (Agility) is recalling certain model Side-Mount compressed natural gas (CNG) Fuel Systems, Part No. 23736011, manufactured August 1, 2013, to August 21, 2014 and equipped with Motion Industries T1700-06 flexible fuel hoses. The stainless steel braid reinforcement may corrode prematurely near the fitting crimp inside the slave tank enclosure.

**Consequence:**

If the corrosion progresses and goes undetected, the hose could begin to leak CNG, increasing the risk of a fire in the presence of an ignition source.

**Remedy:**

Agility will notify owners, and dealers will replace the defective hose assemblies, free of charge. The recall is expected to begin in September 2014. Owners may contact Agility customer service at 1-949-236-5520.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.safercar.gov](http://www.safercar.gov).

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at 202-366-1060, or by email at [michelle.rice@dot.gov](mailto:michelle.rice@dot.gov) or through the office email at [rmd.odi@dot.gov](mailto:rmd.odi@dot.gov). We look forward to working with you.

Sincerely,

A handwritten signature in black ink, appearing to read "Jennifer Timian". The signature is fluid and cursive, with a large initial "J" and a long horizontal stroke at the end.

Jennifer Timian  
Chief, Recall Management Division  
Office of Defects Investigations  
Enforcement