

GM CUSTOMER CARE AND AFTERSALES  
DCS3444  
URGENT - DISTRIBUTE IMMEDIATELY

Date: November 13, 2014

Subject: 14309A – Safety Recall  
Driver Door Switch Short Circuit  
Clarification of Saab Vehicles

Models: 2005-07 Saab 9-7X, 2006 Chevrolet TrailBlazer EXT and GMC Envoy XL, 2006-07 Buick Rainier, Chevrolet TrailBlazer, and GMC Envoy Previously Repaired in Safety Recall 12180.

To: All Buick, Chevrolet, and GMC Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and Service Director, Parts Manager, Used Vehicle Sales Manager, and Warranty Administrator

The bulletin has been revised to inform dealers that owners of Saab 9-7X vehicles delivered in the U.S. or Canada will receive a separate notification and be addressed by Saab Authorized Service Centers. This bulletin applies to Saab vehicles delivered outside of the U.S. and Canada that are subject to this recall.

END OF MESSAGE  
GM CUSTOMER CARE AND AFTERSALES