



After-sales Retailer Support

Takata Front Passenger Air Bag Inflator Voluntary Safety Recall Campaign -Regional Update 3 – Interim Procedure 2006 M35/45

Reference: P4235
Date: January 7, 2015

Attention: Retailer Principal, Sales, Parts and Service Managers

******* Retailer Announcement *******

On November 19th, 2014, Infiniti released an announcement which superseded and consolidated all previous regional voluntary safety recall campaigns for P4235. In that announcement, Infiniti stated that the repair procedure for the affected **M35/45** vehicles was still under development and retailers should contact their FOM should they have a vehicle requiring repairs under this campaign.

This announcement contains an **interim** repair procedure to repair affected **M35/45** vehicles.

******* What Retailers Should Do *******

1. Verify the subject vehicle is affected by this recall campaign using Service Comm **I.D. P4235**.
2. Repair affected vehicles using **ITB14-034**.
 - For M sedan specifically, retailers will replace the front passenger air bag module assembly.
 - Technicians can use the Electronic Service Manual (ESM) to remove and replace the air bag module.
 - Parts and Claims information is included in the attached TSB.

Note: Retailers should use the attached order form to order air bag modules on an as needed basis. Retailers should not stock air bag modules as inflators will be used in the final repair. M sedan inflator availability will be the subject of a separate announcement in approximately 5 weeks.

3. The old front passenger air bag module is subject to the policies outlined in the Assurance Products Resource Manual (APRM), including the Warranty Parts Return Program.
4. Old modules can be returned as outlined in **IPSB/10-029**.

******* Parts Information *******

MODEL	PART DESCRIPTION	PART #	OK TO STOCK	ORDER FORM REQUIRED
M35/45	Passenger Air Bag Module Assembly	Y851E-EH100	No	Yes

******* Claims Information *******

CAMPAIGN ("CM) I.D.	DESCRIPTION	OP CODE	FRT
P4235	M- Replace front passenger air bag module	P42353	2.6 hrs