

GM CUSTOMER CARE AND AFTERSALES
DCS3541
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 10, 2015

Subject: 14171B - Safety Recall
Lapbelt Pretensioner Locking Performance
Revised Part Information Section

Models: 2013 Buick Encore, Cadillac ATS 4-Door, and Chevrolet Trax
AND
Vehicles that were serviced with a suspect part: 2013-2014 Buick Encore,
Cadillac ATS 4-Door, and 2014 Cadillac CTS Sedan (VIN A)

To: All Buick, Cadillac, and Chevrolet Dealers

Attention: General Manager, Service Advisor, Service Manager, Parts and
Service Director, Parts Manager, New Vehicle Sales Manager,
Used Vehicle Sales Manager, and Warranty Administrator

The description of the Tensioner Kit in the Part Information section has been revised. Please discard all copies of bulletin 14171A.

END OF MESSAGE
GM CUSTOMER CARE AND AFTERSALES