



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

April 21, 2015

Mr. Garrett Carolus
Keystone RV Company
17400 Hackberry Drive
Goshen, IN 46526

NVS-215MR
15V-207

Subject: Wheel Studs may Break

Dear Mr. Carolus:

This letter serves to acknowledge Keystone RV Company's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

DUTCHMEN/DENALI/2015
KEYSTONE/SPRINTER/2015

Mfr's Report Date: April 3, 2015

NHTSA Campaign Number: 15V-207

Components:

POWER TRAIN:AXLE HUBS
SUSPENSION:REAR:AXLE:NON-POWERED AXLE ASSEMBLY

Potential Number of Units Affected: 25

Problem Description:

Keystone RV Company (Keystone) is recalling certain model year 2015 Keystone Sprinter trailers, models 252RLS, 269RLS, 295RKS, 298RLS, 299RET, 31BH, and 313BHS, and 2015 Dutchmen Denali trailers, models 2461RK and 262RLX. In the affected trailers, the studs that are used to attach the wheels to the axle hubs may break.

Consequence:

If the wheel studs break, the wheel could detach from the vehicle, increasing the risk of a crash.

Remedy:

Keystone will notify owners, and dealers will replace the wheel hubs, free of charge. The recall is expected to begin in April 2015. Owners may contact Keystone customer service at 1-866-425-4369. Keystone's number for this recall is 15-230.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Michelle Rice who may be reached by phone at 202-366-1060, or by email at michelle.rice@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,



Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement