

Audi of America, Inc.



Date: April 24, 2015

To: Audi Dealer Principal, Service Manager, Warranty Administrator, Sales Manager & Parts Manager

From: Audi Customer Protection

Subject: Upcoming Safety Recall 20V5 – Fuel Delivery Unit
2015 Model Year Audi A3 with Gasoline Engine

We would like to inform you of an upcoming safety recall affecting the fuel delivery unit on certain 2015 model year Audi A3 vehicles equipped with a gasoline engine.

Recall Description: On some vehicles, contamination due to improper nickel plating of certain subcomponents within the fuel pump may cause excessive pump friction, potentially resulting in an inoperative fuel pump. If the fuel pump becomes inoperative due to this condition, it may result in a no-start condition or a stall while driving without warning, and without the ability to restart the vehicle. An engine stall without warning while driving can increase the risk of a crash.

Audi is working diligently to identify affected vehicles and parts needed to support this recall.

Additional information will be provided as soon as it becomes available. If you have any questions or require additional assistance, please contact Warranty. As always, any press inquiries should be directed to Audi Public Relations.

Audi Customer Protection

Audi of America, Inc.
3800 Hamlin Road
Auburn Hills, MI 48326
+1 248 754 5000
www.audiusa.com