

# Federal Recall Information

---

**13KWG**

## Supplier

Kenworth Truck Company

---

## Description

Recall 13KWG – T440 Slip-Resistant Surface for Cab Access Step

---

## Release Date

7/17/2013

---

## Introduction

Kenworth Truck Company has decided that a defect which relates to motor vehicle safety exists in certain Kenworth model T440 vehicles manufactured between June 13, 2012 and March 20, 2013. A total of 19 US chassis and 17 Canadian chassis are involved in this recall. The chassis list and a copy of the customer letter are attached. The DWC and SIR online systems indicate chassis involved in this recall with the designator of “**13KWG**”.

---

## Situation

On T440 models built during the time period indicated above, the forward edge of the tread plate on the cab access step does not extend to the front of the underlying step and, as a result, does not fully align with the cab door opening. A person using the front portion of the step may not encounter sufficient slip resistance during entry to or egress from the cab. Stepping on a surface that is not fully covered by a slip-resistant tread plate could result in a fall and possible injury.

---

## Resolution

- On the affected vehicles that have an M22-1027 cover, remove the cover and replace with an M22-1052 cover.

- On the affected vehicles that have an M22-1027P cover, remove the cover and replace with an M22-1052P cover.

See attached chassis list to determine which cover to order for each chassis.

**It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.**

## Warranty

The DWC system will indicate chassis involved in this recall with the designator of "**13KWG**" in the campaign field.

### Submit Quick Claim 13KWG (Unpolished).

For Field...	Enter...
Failure Location	014-001-012
Failure Type	470 – Wrong Part
Claim Type	C
Campaign Number	13KWG
Labor	SRT 003-XXX @ 0.3 hours
CCC Notes	Recall 13KWG – Replace M22-1027 cover with an M22-1052 cover.

For the two chassis on the attached chassis list that require a **polished** step, submit a standard truck claim per the coding above.

## Parts

See attached chassis list to determine which cover to order for each chassis.

This recall will cover parts purchased through PACCAR Parts (dealer net+ 30% parts mark up) according to the following table:

Quantity	Part Number	Description
----------	-------------	-------------

1	M22-1052	Cover – DPF/SCR Box ( <b>unpolished</b> )
---	----------	---

Or,

Quantity	Part Number	Description
1	M22-1052P	Cover – DPF/SCR Box ( <b>polished</b> )

---

## Labor

This recall will reimburse for 0.30 hours labor to replace the step assembly.

---

## Attachments

 [13KKG Chassis List w/ Part No](#)

 [13KKG US Customer Letter](#)