



U.S. Department of Transportation
**National Highway Traffic Safety
Administration**

1200 New Jersey Avenue SE
Washington, DC 20590

August 25, 2015

Ms. Priscilla Wilkins
Purchasing/Admin Manager
Liftmoore, Inc.
7810 Pinemont Drive
Houston, TX 77040

NVS-215KS
15V-481

Subject: Battery Equalizers-Possible Fire

Dear Ms. Wilkins:

This letter serves to acknowledge Liftmoore, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

LIFTMOORE/6036WX TRUCK CRANE/2001-2006

Mfr's Report Date: July 21, 2015

NHTSA Campaign Number: 15V-481

Components:

ELECTRICAL SYSTEM:BATTERY

Potential Number of Units Affected: 13

Problem Description:

Liftmoore, Inc. is recalling Sure Power Battery Equalizers, part number 12040E00, sold as replacement parts for installation and use on certain 2001 through 2006 6036WX crane trucks. The specific potting compound used in the subject products for insulation was found to be capable of conducting electricity after being exposed to heat.

Consequence:

Once electrically conductive, the material is capable of melting and burning, increasing the risk of a fire.

Remedy:

Liftmoore will notify owners, and dealers will replace any affected battery equalizer, free of charge. The recall is expected to begin in August 2015. Owners may contact Liftmoore customer service at 1-713-688-5533. Liftmoore's number for this recall is 13E-050.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

As stated in Part 573.7, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Your contact for this recall will be Kelly Schuler who may be reached by phone at (202) 366-5227, or by email at kelly.schuler@dot.gov or through the office email at rmd.odi@dot.gov. We look forward to working with you.

Sincerely,

Jennifer Timian
Chief, Recall Management Division
Office of Defects Investigations
Enforcement