



---

08/26/2015

## **New Safety Recall Advanced Communication – R42082615**

FCA US LLC announced a safety recall on certain 2013 through 2015 model year (PF) Dodge Dart vehicles equipped with a Dry Dual Clutch Transaxle (DDCT) (sales code DA1).

Some of the above vehicles have a Transmission Control Module (TCM) mounting bracket that may cause the printed circuit board solder joints to separate, resulting in an electrical open circuit in the TCM. An open circuit in the TCM could cause the transaxle to shift into “Neutral” without warning. Having the transaxle unintentionally shift into “Neutral” under certain driving conditions could cause a crash without warning.

FCA will conduct a voluntary safety recall on all involved vehicles to replace the TCM and the TCM mounting bracket.

Dealers will be notified of the launch of this safety recall by way of established methods used in the past.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries on involved vehicles.

Customer Services Field Operations  
FCA US LLC