



*MAZDA DEALER EMAIL*

*zoom-zoom*

*zoom-zoom*

*zoom-zoom*

August 12, 2015

Attention: Mazda Parts Managers

Subject: Upcoming Safety Recall 8215F

Mazda will soon issue new Safety Recall 8215F for the final driver side air bag inflator repair, but the permanent remedy parts will not be available until later this year.

Recall 8215F appears on eMDCS as PRELIM LTR at this time, but dealers should NOT attempt to place parts orders until 8215F is launched.

Until 8215F is launched, dealers should continue to install the interim replacement parts under Safety Recall 7914J. The current replacement parts for Safety Recall 7914J are an interim repair until final repair parts for 8215F are available.

Please forward this notice to the appropriate personnel at your dealership.

Mazda Technical Services Department