



Gulf Stream Coach Incorporated
503 South Oakland Avenue
Nappanee, Indiana 46550

Phone (574) 773-7761 - Fax (574) 773-5761

Kenneth N. Weinstein
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, D.C. 20590

7 AUG 08

PART 573 - DEFECT INFORMATION REPORT

08V-411
(2 pages)

1 Manufacturer's name & address:

Gulf Stream Coach, Inc.
P.O. Box 1005
Nappanee, IN 46550

2. Vehicles Involved:

The vehicles covered by this Report are recreational vehicles that were equipped with certain models of refrigerators manufactured by Dometic Corporation between June 2003 and September 2006. The vehicle model numbers and model family names are on the attached spreadsheet. Model years include 2004, 2005, 2006, & 2007.

The vehicles were manufactured during the period from 1 JUN 03 through 31 OCT 06.

3. Total number of vehicles:

The total number of vehicles covered by this report is 31,733 (26,847 non-Canadian & 4,886 Canadian).

4. Approximate percentage of vehicles estimated to actually contain the defect:

Based on information received from Dometic, Gulf Stream Coach believes that approximately .005 percent of these vehicles actually contain the defect.

5. Description of the defect:

Under some circumstances, a fatigue crack can develop in the boiler tube of the covered refrigerators, which can permit the release of pressurized coolant solution. If this solution is exposed to an ignition source under certain specific circumstances, it can result in a vehicle fire.

6. Chronological summary of events leading to this determination:

Dometic advised Gulf Stream Coach, Inc. of its defect determination by letter received 20 JUN 08

7. Program for remedying the defect:

Dometic has arranged to conduct a recall to remedy the potential defect in Gulf Stream Coach, Inc. vehicles at no charge to vehicle owners. See Recall No. 08E-032. Pursuant to 49 CFR 573.6(c)(8)(i) and 573.13, owners will be advised that Dometic will reimburse them if they have incurred costs to obtain a remedy for a refrigerator containing such a defect prior to their receipt of the notification. On 7 AUG 08, Gulf Stream supplied the database of vehicle & owner information to Stericycle, whom Dometic has contracted with to conduct the recall.

Jeffrey C. Satoski
Compliance Engineer
Gulf Stream Coach, Inc.

RECEIVED

2008 AUG 15 A 10:35

DEFECTS INVESTIGATION
RECALL MGMT DIV.

MOTORIZED PRODUCTS		
Model Numbers		Model Names
4230	8333ILT	Atrium
4231	8335MXG	B Touring Cruiser
4270	8336DH	Cavalier
5210	8351MXG	Conquest
5211	8353RH	Crescendo
5230	8356CRE	Endura
5231	8357I	Friendship
5250	8358I	Independence
5270	8359DH	Palm Breeze
5271	8360RH	Scenic Cruiser
5272	8361I	Sun Sport
5290	8368MXG	Sun Voyager
5291	8370SPE	Tour Master
6211	8376CH	Ultra
6236	8377MXG	Yellowstone
6244	8378I	
6245	8379LXG	
6254	8386CRE	
6255	8387FS7	
6275	8388LXG	
6276	8389LXG	
6280	8390CRW	
6295	8408CRE	
6296	8410SE	
6301	8411FS7	
6316	8412FS8	
6317	8414FS8	
6318	8708FS7	
6319	8710CRE	
6331	T36	
6340	T40	
6341	T41	
6361	T42	
6362	T44	
6370		
6378		
324FRED		
351FRED		
361FRED		
368FRED		
368YFED		
378FRED		
389YFED		
8292DH		
8295I		
8301CH		
8314I		
8320CH		
8326LS		
8328C		
8329MXG		
8330I		

TOWABLE PRODUCTS				
Towable Model Numbers				Model Names
3105	24TRTH	28FWBH	31TRBH	Ameri-Lite
16DBL	2511D	28RB	31TRBW	Canyon Trail
17FD	255BWL	28RBG	325FKS	Cavalier
18DBG	255RB	28TBR	325PBS	Conquest
19BH	25BH	28TRBW	325QBS	Emerald Bay
19EXP	25BW	28TRK	32BHS	Gulf Breeze
19FDL	25FRBW	28TRS	32FBHW	G-Force
19RBH	25LS	28TRTH	32RLF	Innsbruck
19RDB	25RB	2911D	32TBHS	Kahuna Bay
200BH	25RBS	295DB	3311D	Kingsport
20BHL	25RKS	295DBR	33FBHT	Mako
20DGT	25RSL	295DBS	33RKFW	Mini
20GBH	260BH	295RLS	34FBR	Prairie Schooner
21FBS	265BHS	297FWB	34FLR	Seahawk
21FMB	265FKS	298DBS	34FMT	Sedona
21FMS	265RL	299TBR	34FSBW	Side Kick
21MB	265RTH	29BHS	35FBS	Side Track
21SS	265TBS	29DBS	35FDBH	Stream-Lite
220GF	266RL	29FBW	36FKS	Track & Trail
225RTH	267BW	29FKS	36FLS	Trailmaster
22BH	268BW	29FRBW	36FLSS	Wide Open
22FB	26BWS	29FRK	36FMS	Yellowstone
22FBH	26EXP	29QBH	36FQS	
22SS	26FBH	29RGS	36FRB	
231EXP	26FBHD	29RKFW	36FRS	
235BH	26FBHS	29RL	36FRS	
236RB	26FBL	29RLF	36FSK	
23DBG	26FGTS	29SBW	36MAX	
23DBQ	26FRBW	29SSS	380FRS	
23EXP	26QBS	29TBW	381FRS	
23FRBL	26RBS	29TRB	38MAX	
23GBH	26RLS	29TRBH	4002B	
23RTH	26SBW	29TREB	525DBS	
23TRS	26SSL	301TB	531BH	
240GF	26TRK	30BHS	531RL	
2411D	26TRS	30FBHS	532SS	
245BH	275FB	30FBRG	7290TT	
245RB	275FBD	30FSK	7330MAX	
24BH	275FBS	30FSSS	7370MAX	
24BHL	275FS	30QBS	7380MAX	
24FBL	275GTS	30QBSS	7381MAX	
24FBS	275RGT	30RGT		
24FBW	27FKDS	30RLF		
24FRBW	27FRBW	30TBR		
24FTBS	27TRBW	30TDS		
24QS	280GF	30TRET		
24RB	285RLS	3105GF		
24RBL	286RLS	3111D		
24RKSL	28EXP	315FKS		
24RS	28FBHS	31FRBH		
24SS	28FRBH	31FTS		
24TB	28FRGT	31TBRG		