



**IC Bus, LLC**  
4201 Winfield Road  
Warrenville, IL 60555 USA

navistar.com

A NAVISTAR COMPANY

## **SAFETY RECALL G-08502**

**NOVEMBER 2008**

Dear IC Bus Customer,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

IC Bus has decided that a defect which relates to motor vehicle safety exists in certain 3000, CE, FE, and RE bus models built 6/1/06 thru 6/30/07 with DT466 or DT570 engines.

### ***REASON FOR THIS RECALL***

The engine oil cooler base may crack which could result in sudden loss of engine oil.

### ***RISK TO MOTOR VEHICLE SAFETY***

This condition may result in engine fire, sudden engine shutdown, or loss of vehicle control due to oil on the roadway.

### **ACTIONS YOU SHOULD TAKE**

Please contact your IC Bus dealer to schedule an appointment to have your vehicle repaired. Your nearest dealer may be located by calling 1-800-448-7825 or by visiting <http://www.navistar.com>.

The repair will involve replacement of the engine oil cooler.

Dealers will have parts and instructions to repair your vehicle by 11/14/08.

This repair will be performed free of charge and may take approximately 90 minutes to complete.

### **IF YOU DO NOT OWN THIS VEHICLE**

IC Bus' records indicate you are the owner of the vehicle identified on the enclosed Authorization for Recall Service card. If you do not own this vehicle, please fill out and return mail the card so that you will not be contacted again about this recall.

### **IF YOU NEED ASSISTANCE**

If you believe that IC Bus has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9152); or go to <http://www.safercar.gov>.

### **LESSOR REQUIREMENTS**

Federal regulations require that any vehicle lessor receiving this Recall Notice forward a copy of it to the lessee within ten days.

IC Bus requests your prompt attention and patience regarding the correction of this defect and apologizes for any inconvenience this may cause you.

**IC Bus, LLC**