

K2 Motor/Spec D Tuning  
250 Benton Ct.  
Walnut, CA 91789

Dec 17, 2008

RE: Recall of lamps mounted at or near the front of the vehicle

Dear K2 Motor/Spec D Tuning Lamp Purchaser:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

K2 Motor/Spec D Tuning has decided that certain K2 Motor/Spec D Tuning's suppliers' lamps fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 108, "Lamps, Reflective Devices, and Associated Equipment." These lamps do not come with the amber side reflex reflectors. Without the amber side reflex reflectors, it will affect or decrease the lighting visibility. Decreased lighting visibility may result in a vehicle crash. The attached list (LIST 1 Revised) is a list of the part numbers, make and model of the lamps.

If your original lamp was manufactured without the amber side reflex reflectors, you will need to replace the lamp with amber side reflex reflectors. If you have purchased one of these lamps on and after January 1, 2004, please contact our Returns Department at 909-839-2992 to initiate the return and refund process. The return of the identified products will be handled free of charge and the refund will be credited to your account.

If you have any problems with the return and obtaining the applicable credit, please call and ask to speak to a senior account executive at 909-839-2992. K2 Motor/Spec D Tuning is fully devoted to addressing any problems that may arise as the result of this recall.

If, after calling us, you still feel that K2 Motor/Spec D Tuning has not provided you with a free remedy to the situation within a reasonable amount of time, you may submit a complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590 or call 1-888-327-4236 (TTY: 1-800-424-9153); or go to <http://www.safercar.gov> for more information.

We apologize for any inconvenience that may cause you. However, in the best interests of consumer safety, it is our desire to resolve this issue immediately.

Thank you for your attention this matter!

K2 Motor/Spec D Tuning