



April 6, 2009

Associate Administrator for Safety Assurance (NSA-11)
National Highway Traffic Safety Administration
400 7th Street, SW
Washington, DC 20590
Attn.: Mrs. Kelly Schuler

Re: Recall No. 02V-295 Quarterly Report, (re-inspect recall 00V-025 Roadrailer crossmember cracking at front of body rails.)

Dear Mrs. Kelly Schuler,

Attached is the 1st quarterly report for the year 2009 on Recall No. 02V-295.

This report shows an additional 14 units completed from the last report for a total of 5389 out of the 6065 needing to be inspected. The report also shows that all customers have been notified of the re-inspection. One repair facility in the U.S. is actively inspecting all units available. All Canadian units have now been completed.

If there are any other issues that you feel we must address, please contact me. Our intent is to fully comply with all regulatory requirements. I can be reached at 765-771-5404 or by email at "jgabriel@wabashnational.com". Thank you for your assistance in this matter.

Sincerely,

John Gabriel II
Customer Service

Vehicle Safety Recall Quarterly Report Information

Report Date: 4/6/2009

Calendar Quarter: First

Safety Recall Quarterly Report from January 1, 2009 thru March 31, 2009

Manufacturer: Wabash National Corp.

Report Author: John Gabriel Phone: 765-771-5404

Recall Subject: Re-inspect recall 00V-025 (RoadRailer crossmember cracking at front of body rails.)

1. NHTSA Safety Recall Campaign Number: 02V-295

Wabash Recall Number: SB2000-001

2. a) The date notification to purchasers began: October 2002

(b) The date notification of purchasers was completed: October 2002

3. The Total Number of Vehicles Involved: 6065

4. (a) Total Number Inspected & Remedied: 1725

(b) Total Number Inspected & Not Requiring Remedy: 3664

5. Vehicles Determined to be Unreachable:

Total Number Exported: 320 (Canadian units)

Total Number Stolen: 0

Total Number Scrapped: 127

Total Number Unable to Notify: 0

Total Number Otherwise Unreachable: 0