

TO: Winnebago Industries, Inc. Dealers
SUBJECT: Campaign #112 – Propane Tank Bracket

The National Traffic and Motor Vehicle Safety Act, as amended, provides that each vehicle which is subject to a recall campaign of this type must be adequately repaired within a reasonable time after the owner has tendered it for repair. A failure to adequately repair within 60 days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time.

If the condition is not adequately repaired within a reasonable time, the owners may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation.

To avoid having to provide these burdensome solutions, every effort must be made to promptly schedule an appointment with each owner and to repair their vehicle as soon as possible. As you will see in reading the enclosed copy of the letter which is being sent to owners, the owners are being instructed to contact Winnebago Industries, Inc. if you do not remedy the condition within five days of the mutually agreed upon service date. If the condition is not remedied within a reasonable time, they are instructed on how to contact the National Highway Traffic Safety Administration.

REASON FOR THIS RECALL

Winnebago Industries, Inc. has decided that a defect which relates to motor vehicle safety exists on certain 2002, 2003, and 2004 model years Winnebago Brave® and Itasca Sunrise®; 2005 and 2006 model years Winnebago Voyage® and Adventurer® and Itasca Sunrise® and Suncruiser®. These motor homes were manufactured November 5, 2001 through April 27, 2006. The propane tank mounting bracket may have an incomplete or improper weld. Should the weld fail, the propane tank can tip or fall, possibly releasing propane which has the potential to ignite, resulting in personal injury and/or vehicle and property damage.

OWNER NOTIFICATION

Owners will be notified of this campaign on their vehicles by Winnebago Industries, Inc. For all units in your inventory, the notification will be mailed to you. **DO NOT DELIVER TO A CUSTOMER ANY SUBJECT UNIT UNTIL CORRECTIVE ACTION HAS BEEN TAKEN.** Enclosed is a list of vehicles shipped to you.

DEALER CAMPAIGN RESPONSIBILITY

Dealers are to service all vehicles subject to this campaign at no charge to owners regardless of mileage, age of vehicle, or ownership from this time forward.

Whenever a vehicle subject to this campaign is taken into new or used vehicle inventory or it is in your dealership for service in the future, you should take the steps necessary to be sure the campaign correction has been made before reselling or releasing the vehicle. Owners of vehicles recently sold from your new vehicle inventory are to be contacted by the dealer and arrangements made to make the required correction according to instructions contained in this campaign.

INSTRUCTION TO PERFORM CAMPAIGN # 112

Affected Models:

- 2002 model year Winnebago Brave and Itasca Sunrise, Model F34D.
- 2003 model year Winnebago Brave and Itasca Sunrise, Models F34D and F36M.
- 2004 model year Winnebago Brave and Itasca Sunrise, Models F34D and F36M.
- 2005 model year Winnebago Voyage and Itasca Sunrise, Models F35A, F35D, and F36M and Winnebago Adventurer and Itasca Suncruiser, Model G35A.
- 2006 model year Winnebago Voyage and Itasca Sunrise, Models F35A and F35D (built prior to May 1, 2006) and Winnebago Adventurer and Itasca Suncruiser, Model G35A (built prior to May 1, 2006).

Repair Procedure:

Refer to instruction sheet for inspection and repair of propane tank bracket welds.

REIMBURSEMENT

When the service has been completed, submit the labor amount and labor operation number listed below. Your repair order must be properly signed by both the dealer and the owner.

	OPERATION NUMBER	TIME ALLOWANCE
INSPECTION OF PROPANE TANK BRACKET	<u>24120101</u>	<u>.4 Hr.</u>
- or -		
INSPECTION AND REPAIR OF PROPANE TANK BRACKET	<u>24120201</u>	<u>.4 Hr. Plus Approved Straight Time</u>

Thank you for your cooperation.

Winnebago Industries, Inc.
Forest City, Iowa 50436

RP129/4

Enclosures