



HYUNDAI DE PUERTO RICO  
C/O MMSC  
Road 2 Km. 20.1, Candelaria Ward, Toa Baja, PR 00948  
P.O. Box 192216, San Juan, PR 00919-2216  
Tel. (787) 999-4310 Fax (787) 251-3024 / 8700  
www.hyundai-pr.com

AFFECTED VEHICLES:  
2008 ELANTRA

Date: February 2009

51\_08V694\_HD.FPUMP\_6U395212

**RE : IMPORTANT SAFETY RECALL NOTIFICATION**  
(Fuel Pump Subassembly Replacement – Recall No. 08V-694)

**VIN : KMHDT46D08U395212**

Dear 2008 Elantra Owner:

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Hyundai has decided that a defect, which relates to motor vehicle safety, exists in certain model year 2008 Hyundai Elantra vehicles that were produced during the period beginning November 5, 2007 through June 28, 2008.

**What is the problem?**

The fuel pump motor may not have the proper, uniform internal electrical surface contact. This may cause the fuel pump to produce less pumping pressure than required to supply the fuel injection system. As a result, poor engine starting and hesitation may result. Other engine performance issues may also result and lead to a crash.

**What will Hyundai do?**

To ensure that your vehicle's fuel pump operates properly, we are asking you to schedule an appointment as soon as possible to take your vehicle to your Hyundai dealer. The Hyundai dealer will replace your vehicle's fuel pump subassembly. This procedure will be performed at no charge to you. The time needed for the actual repair is approximately half an hour, but you should plan to leave your vehicle at your Hyundai dealer to have this service performed. Repair times will vary and depend on your dealer's appointment schedule.

**What should you do?**

We urge you to call your Hyundai dealer to schedule an appointment to have this work performed as soon as possible.

If you have already encountered the problem described above and you have paid for the repairs, please call Hyundai of Puerto Rico at 1-800-981-0188 for counsel on a possible reimbursement.

**What if you have other questions?**

If you have any difficulty having this repair performed, we recommend that you call the Hyundai of Puerto Rico Customer Service at 1-800-981-0188. If you are still not satisfied that we have remedied this situation without charge, and within a reasonable amount of time, you may wish to write to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, D.C. 20590, or call their toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153), or go to the web site <http://www.safercar.gov>.

We urge your prompt attention to this safety matter.

Hyundai of Puerto Rico