

Johnson, Valencia (NHTSA)

From: McHenry, Stephen (NHTSA)
Sent: Wednesday, July 29, 2009 10:43 AM
To: Johnson, Valencia (NHTSA)
Subject: Memo to File: PE09-033

From: Stephen.McHenry@dot.gov [mailto:Stephen.McHenry@dot.gov]
Sent: Tuesday, July 28, 2009 3:39 PM
To: Nevi, Raymond (R.A.)
Subject: PE09-033

Ray,

I have a correction to make to the VOQs related to PE09-033 as listed in the IR: based on interviews with owners the following VOQs, listed as one of the original 65 complaints related to torque convertor failure, are duplicates or not related to the subject defect.

10212191
10213550
10243483
10268178

Based on owner interviews, the following VOQs are now being considered as being related to the torque convertor failure:

10222053
10262197
10277558
10277615
10278143
10278244

I have attached a PDF with copies of the VOQs not previously supplied to Ford.

Regards,
Steve

Stephen McHenry
Investigator, US D.O.T.
National Highway Traffic Safety Administration
Office of Defects Investigation
NVS-213 Room W48-217
1200 New Jersey Ave., SE
Washington D.C. 20590-0001

202.366.4883 or 1.877.536.8368 x-64883
Fax 202.366.3171