



AMERICAN SUZUKI MOTOR CORPORATION



July 29, 2009

Mr. Daniel C. Smith
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, D.C. 20590

Dear Mr. Smith

Subject: Recall Campaign Quarterly Status Reports

Enclosed are quarterly status reports for the following recall campaigns:

- 1) Campaign No. 07V-554; Sixth Quarterly Status Report
- 2) Campaign No. 08V-249; Fifth Quarterly Status Report
- 3) Campaign No. 09V-022; Second Quarterly Status Report
- 4) Campaign No. 05V-566; Eighth Quarterly Status Report
- 5) Campaign No. 06V-025; Eighth Quarterly Status Report

Please contact me if you have any questions regarding this information.

Sincerely,
AMERICAN SUZUKI MOTOR CORPORATION

Kenneth M. Bush
Associate Director
Government Relations

Vehicle Safety Recall Quarterly Status Report

Required per 49 CFR Part 573.7

Report Date: July 29, 2009 Calendar Quarter: 2nd

Safety Recall Quarterly Report from April 1, 2009 through June 30, 2009

Manufacturer Name: American Suzuki Motor Corporation

Report Author: Ken Bush Phone: (714) 996-7040 ext. 2207

Recall Subject: 1998-2006 VL1500 Fuel Tank Mount Kit

1. NHTSA Safety Recall Campaign Number: 06V-025

Suzuki Campaign Number: 2087

2. (a) The date notification to purchasers began: Initial owner notification letters were sent on February 3, 2006. Follow-up notification letters were sent on January 23, 2009.

(b) The date notification of purchasers was completed: January 23, 2009

3. The Total Number of Vehicles Involved: 37,511

The total number of vehicles involved in the subject campaign (including all items sold or distributed to purchasers, dealers, distributors, and similar entities beyond the immediate control of the manufacturer/importer).

4. (a) Total Number Inspected & Remedied: 24,255

Total number of vehicles which were inspected and/or otherwise repaired or remedied.

(b) Total Number Inspected & Not Requiring Remedy: 0

Total number of vehicles involved in the recall and inspected, but determined to not require remedial or recall repair work.

5. Vehicles Determined to be Unreachable

Number Exported: 45

Number Stolen: 0

Number Scrapped: 10

Number of Undeliverable Notification Letters: 801 (Second Notification)

Number Otherwise Unreachable: 69

Describe Other: _____