



Navistar, Inc.
4201 Winfield Road
Warrenville, IL 60555 USA

navistar.com

RECEIVED
By Recall Mgt Div. at 8:21 am, Mar 02, 2010



A NAVISTAR COMPANY

SAFETY RECALL G-08505

FEBRUARY 2010

RECALL REMINDER – 2ND NOTICE

Dear INTERNATIONAL® Customer,

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

This is a safety recall **follow-up** notification to the initial notice mailed in July 2008. Navistar's records indicate the vehicle identified on the enclosed Authorization for Recall Service card has not been repaired. If it has been repaired, please fill out and return mail the card so you will not be contacted again about this recall.

Navistar has decided that a defect which relates to motor vehicle safety exists in certain 3000, 4000, 7000, 8000, CXT, MXT, and ProStar models built 11/21/00 thru 5/21/08 with one or more remote power modules.

The repair will involve the installation of a fused electrical cable in the remote power module's ground circuit. Dealers have parts and instructions to repair. This repair will be performed free of charge and takes approximately 30 minutes to complete.

IF YOU DO NOT OWN THIS VEHICLE

If you do not own the vehicle identified on the enclosed Authorization for Recall Service card, please fill out and return mail the card so that you will not be contacted again about this recall.

IF YOU NEED ASSISTANCE

If you believe that Navistar has failed to perform this repair within a reasonable amount of time, or the existing condition was not remedied without charge, please follow the procedure described in the Owner Assistance Guide section in your Owner's Manual or call toll free 1-800-448-7825.

You may also submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Ave, SE, Washington, DC 20590; or call the toll free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9152) or go to <http://www.safercar.gov>.

LESSOR REQUIREMENTS

Federal regulations require that any vehicle lessor receiving this Recall Notice forward a copy of it to the lessee within ten days.

REASON FOR THIS RECALL

Water and contamination intrusion through the material that encapsulates the circuit board may cause an electrical short inside the remote power module.

RISK TO MOTOR VEHICLE SAFETY

An electrical short within the remote power module housing may cause a fire, which can result in property damage, personal injury, or death.

ACTIONS YOU SHOULD TAKE

Please contact your local INTERNATIONAL® dealer to schedule an appointment to have your vehicle repaired. Your nearest dealer may be located by calling 1-800-448-7825 or by visiting <http://www.navistar.com> and clicking on the INTERNATIONAL® logo icon.

Navistar, Inc.