

DAIMLER

Daimler Trucks North America
Nasser Zamani
Senior Manager
Compliance and Regulatory Affairs

February 2, 2010

Dan Smith
Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
1200 New Jersey Avenue S.E.
Washington D.C. 20590

**Re: Defect Information Report – Supplemental Report No. 10
07V-403, FL-513, Rack and Pinion Steering – Steering Stops**

Mr. Smith,

In accordance with Part 573 of Title 49 of the Code of Federal Regulations, Daimler Trucks North America LLC herewith submits supplemental defect information and copies of documents distributed to dealers and purchasers.

- (c)(3) Total number of vehicles potentially affected: 176
- (c) (8)(ii) Communications sent to dealers: posted January 30, 2010
Communications will be sent to owners by: February 12, 2010
- (c) (10) Copies of Communications sent to owners and dealers are attached.

Please contact me if you have any questions.

Sincerely yours,



Nasser Zamani

Cc: Michael Mason, CAL-OSHA
Enclosure
Certified Mail# 70063450000038668253

A Daimler Company

Daimler Trucks North America LLC
4747 N. Channel Avenue
Portland OR 97217-7699
503-745-6910 Phone
503-745-5544 Fax
Nasser.Zamani@Daimler.com

Enclosures:

Work Instructions -

FL-513 A-Y
FL-513CD
FL513EF
FL513GH
FL513I
FL513J
FL513K
FL513L
FL513M
FL513N
FL513O
FL513P
FL513Q
FL513R
FL513S
FL513TUVW
FL513X
FL513Y