

# Daimler Trucks North America LLC

Daimler Trucks North America LLC  
P.O. Box 4090  
Portland, OR 97208-4090  
800.547.0712 Phone  
503.745.9009 Fax

April 2010  
**FL527AB**  
NHTSA #08V-137  
REMINDER NOTICE

## Subject: Medium Duty Axle Spindle Nuts

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. This notice is also sent in accordance with the Canadian Motor Vehicles Safety Act.

Daimler Trucks North America LLC, on behalf of its Freightliner Trucks Division and its wholly owned subsidiaries, Sterling Truck Corporation and Freightliner Custom Chassis Corporation, has decided that a defect which relates to motor vehicle safety exists on specific Freightliner Business Class and Business Class M2; Sterling Acterra; and Freightliner Custom Chassis FS65 and B2 (Thomas Built Buses C2 Saf-T-Liner) school bus chassis and FB65 shuttle bus chassis manufactured between January 26, 2000, and March 24, 2008, by ArvinMeritor or Axle Alliance Company with 6,000 or 8,000 pound front axles and a four-piece spindle nut set.

Installation of a four-piece spindle nut set with a thin spindle nut may lead to damage of the wheel end, including incorrect end play, degradation of lubrication, wear of the spindle nut and bearing journal, oil contamination with metal shavings, and premature bearing failure. Outer wheel bearing failure will cause noise and vibration that will be noticeable to the driver and the Antilock Braking System warning light will illuminate. Continued operation with the warning light illuminated may result in wheel separation and a possible vehicle crash.

The existing four-piece spindle nut set will be replaced with a more robust nut set using a thicker, harder inner nut and a new hub cap will be installed.

**Our records indicate that your vehicle(s) has not yet had this recall performed. Please make arrangements to have this repair done as soon as possible. If it has been completed, please disregard this letter.**

Parts are now available for authorized dealers to order. Contact your authorized dealer to arrange to have your vehicle(s) modified and to assure that parts are available at the dealer. To locate a dealer, search online at [www.FreightlinerTrucks.com](http://www.FreightlinerTrucks.com), [www.SterlingTrucks.com](http://www.SterlingTrucks.com), or contact the Warranty Campaigns Department for assistance.

When you contact your dealer, refer to campaign number **FL527AB**. Once parts are received at the dealership, the recall will take approximately two to three and a half hours, depending on the work needed, and will be performed at no charge to you.

**IMPORTANT:** When the Recall has been completed, please ensure that a label has been affixed to your vehicle referencing **FL527AB**.

If you do not own the vehicle that corresponds to the identification number(s) which appears on the Recall Notification, please return the notification to the Warranty Campaigns Department with any information you can furnish that will assist us in locating the present owner. If you have leased this vehicle, Federal law requires that you forward this notice to the lessee within 10 days. If you are a subsequent stage manufacturer, Federal law requires that you forward this notice to your distributors and retail outlets within five working days.

If you are not able to have the defect remedied without charge and within a reasonable time, which is not longer than 60 days after you tender the vehicle for repair, please contact the Warranty Campaigns Department at (800) 547-0712, 7:00 a.m. to 4:00 p.m. Pacific Time, Monday through Friday, e-mail address [DTNA.Warranty.Campaigns@Daimler.com](mailto:DTNA.Warranty.Campaigns@Daimler.com), or the Customer Assistance Center at (800) FTL-HELP or (800) STL-HELP, after normal business hours. You may also wish to submit a complaint to the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590; or call the Vehicle Safety Hotline at (888) 327-4236 (TTY: 800-424-9153); or to <http://www.safercar.gov>. If your vehicle is involved in the Canadian portion, you may wish to notify Transport Canada, ASFAD, Place de Ville Tower C, 330 Sparks Street, Ottawa, ON K1A 0N5, or phone (800) 333-0510.

We regret any inconvenience this action may cause but feel certain you understand our interest in motor vehicle safety.

WARRANTY CAMPAIGNS DEPARTMENT

Enclosure