

October 25, 2010

Ms. Jennifer T. Timian
Acting Chief, Recall Management Division
Office of Defects Investigation Enforcement
National Highway Traffic Safety Administration
400 Seventh Street, SW
Washington, DC 20590

Re: Defect Information Report: SunnyBrook RV, Inc. vehicles equipped with
Certain Dimplex electric fireplaces

Dear Ms. Timian,

SunnyBrook RV has been advised by Dimplex Ltd North America that certain plug-in remote control receivers that were included with certain Dimplex electric fireplaces have a defect that relates to motor vehicle safety because in some instances they may overheat, posing a fire hazard. On the basis of that Dimplex determination, SunnyBrook RV has decided that there may be a potential safety defect in its vehicles equipment with the identified fireplaces, and we are therefore submitting the enclosed Defect Information Report pursuant to 49 CFR Part 573.

If you have any questions, please do not hesitate to contact me by phone at (574) 825-5250 ext 5119 or by email as sheldon.troyer@sunnybrookrv.com.

Sincerely,



Sheldon Troyer
Controller

Enclosure

DEFECT INFORMATION REPORT

1. Manufacturer's name/address

The manufacturer of the vehicles covered by this Report is:

SunnyBrook RV, Inc.
201 14th Street
P.O. Box 2001
Middlebury, IN 46540

2. Vehicles involved:

The vehicles covered by this Report are SunnyBrook RV recreational vehicles that were equipped with certain fireplaces manufactured by Dimplex. The vehicle models in question are as follows: Bristol Bay, Titan and West Pointe series.

The vehicles were manufactured during the period from October 2002 through May 2008.

3. Total number of vehicles:

The total number of vehicles covered by this Report is 608.

4. Approximate percentage of vehicles estimated to actually contain the defect:

We cannot determine if a vehicle is affected without inspecting the vehicle.

5. Description of the defect:

In some instances, the plug-in remote control receiver, which is a component of a factory fireplace, can overheat, posing a fire hazard.

6. Chronological summary of events leading to this determination:

SunnyBrook RV received a notice from NHTSA regarding the Dimplex recall. SunnyBrook RV contacted WESCO (SunnyBrook's distributor for Dimplex products) asking for the details of the recall. It was discovered that SunnyBrook RV had been notified by WESCO about the recall, but the information did not get delivered to the proper department. SunnyBrook RV is now in regular communication with WESCO and Dimplex regarding the ongoing recall.

7. Program for remedying the defect:

Dimplex has notified SunnyBrook RV that they will be handling the entire recall on SunnyBrook RV's behalf; they will be able to handle the process more efficiently. After reviewing the recall, SunnyBrook RV agrees that it will be a more efficient and effective recall if Dimplex handles the process. SunnyBrook is forwarding a list of potentially affected vehicles, their corresponding VINs, and any potential retail contact information for each vehicle.



Sheldon Troyer
Controller