

November 2, 2010

Mr. Daniel C. Smith  
Associate Administrator for Enforcement  
NATIONAL HIGHWAY TRAFFIC SAFETY  
ADMINISTRATION  
Attn: Recall Management Division (NVS-215)  
1200 New Jersey Avenue, SE  
Washington, DC 20590

**Re: Recall Notification  
2005-07 Model Year Acura RL; 2005-07 Honda Odyssey  
Brake Master Cylinder**

Dear Mr. Smith:

This will amend our Part 573 Report dated October 21, 2010 by providing the following updated and additional information regarding the Voluntary Recall 10V-504.

573.6(c)(2)

**Identification of potentially affected vehicles:**

<u>Make/Model</u>	<u>Description</u>	<u>VIN Range/Dates of Manufacture</u>
Honda Odyssey	Certain 2005 model year	5FNRL38445B000146 – 5FNRL386X5B136928 June 22, 2004 to August 8, 2005
		5FNRL38445B400014 – 5FNRL38615B425597 October 14, 2004 – August 5, 2005
		5FNRL38485B503419 December 22, 2004
Honda Odyssey	Certain 2006 model year	5FPRL484X5B129215 – 5FPRL48465B129244 July 21, 2005
		5FNRL38856B000001 – 5FNRL38646B129961 August 2, 2005 to August 21, 2006
Honda Odyssey	Certain 2007 model year	5FNRL38627B000201 – 5FNRL38707B068053 August 8, 2006 to April 3, 2007
		5FNRL384X7B400201 – 5FNRL38427B441549 August 9, 2006 to April 4, 2007

573.6(c)(3)

**Total number of potentially affected vehicles:** approx. 500,000

573.6(c)(8)(ii)

**The estimated date to e-mail preliminary notification to dealers:** Oct. 21, 2010

**The estimated date to provide service bulletin to dealers:** Nov. 6, 2010

**The estimated date to begin sending notifications to owners:** late Dec. 2010

**The estimated date of completion of the notification:** late Jan. 2011

573.6(c)(11)

**Manufacturer's campaign number:**

R51 (Honda Odyssey), R52 (Acura RL)

Sincerely,

AMERICAN HONDA MOTOR CO., INC.



Jay Joseph  
Senior Manager  
Product Regulatory Office

JWJ:nis