

# DAIMLERCHRYSLER

RECEIVED  
NVS-215

DaimlerChrysler Manufacturing International LLC

2003 JUL 14 A 11:42

OFFICE OF  
DEFECTS INVESTIGATION

Richard R. Shyu  
Manager of Compliance  
Tel: 704-655-1052  
Fax: 704-655-1055  
e-mail: [richard.shyu@dcx.com](mailto:richard.shyu@dcx.com)

via FedEx

July 11, 2003


Office of Defects Investigation, Room 5326  
National Highway Traffic Safety Administration  
400 Seventh Street, S.W. (NSA-01)  
Washington, D.C. 20590  
Attention: George Person

Subject: **49 CFR 573.7 Recall Quarterly Report**  
(NHTSA Assigned Recall No. 03V-082)

Dear Mr. Person,

On behalf of our parent company, DaimlerChrysler AG in Germany, we would like to submit herewith, our first Part 573.7 quarterly report, covering the second calendar quarter ending June 30, 2003. The subject recall campaign concerns airbag of certain model year 2003 Sprinter vehicles.

Sincerely,



Enclosure

# DAIMLERCHRYSLER

DaimlerChrysler Manufacturing International LLC

Date: July 11, 2003

## 49 CFR 573.7 Recall Quarterly Report

- For the Second Calendar Quarter of 2003

To: Associate Administrator for Enforcement (NSA01)  
National Highway Traffic Safety Administration  
400 7<sup>th</sup> Street, S.W.  
Washington, DC 20590

MANUFACTURER: DaimlerChrysler AG, Stuttgart, Germany

Designated Agent: Wolf-Dieter Kleirneier  
DaimlerChrysler Manufacturing International LLC  
8936 NorthPointe Executive Dr., Suite 200  
Huntersville, NC 28078  
Tel: 704-655-1050  
Fax: 704-655-1055

### INFORMATION REQUIRED:

(b)(1) Notification Campaign Number:	03V-082
(b)(2) Owner Notification- Date started:	April 18, 2003
Date Completed:	April 18, 2003
(b)(3) Number of Vehicles Involved in Campaign:	281(March 4 Estimated) 250(April 3 Revised)
(b)(4) Number of Vehicles Inspected & Repaired:	240
Number of Vehicles Inspected/Not Needing Repair:	0
(b)(5) Number of Vehicles Unreachable for Inspection:	2
Reason: Scrapped	
(b)(6) Number of Quarters Recall Has Been in Effect:	1