

TOYOTA

TOYOTA MOTOR NORTH AMERICA, INC.

WASHINGTON OFFICE
601 THIRTEENTH STREET, NW, SUITE 910 SOUTH, WASHINGTON, DC 20005

TEL: (202) 775-1700

FAX: (202) 463-8513

March 25, 2011

Mr. Daniel C. Smith
Senior Associate Administrator for Vehicle Safety
National Highway Traffic Safety Administration
1200 New Jersey Avenue, S.E.
Washington, D.C. 20590

RE: Recall 09V-388 (9LG/90L) (11V-113)
Amended Part 573 Notification: Certain Toyota and Lexus Vehicles
Potential Floor Mat Interference with Accelerator Pedal


Dear Mr. Smith:

In connection with the above referenced matter, this supplements Toyota's letter of February 24, 2011. Toyota is now providing some additional vehicle information as follows:

| Make/ Car Line | Model Year | Manufac -turer | VIN | | Production Period | Population |
|--------------------|---------------|-------------------|-------|---|---|------------|
| | | | VDS | VIS | | |
| Toyota/ 4Runner | 2003- 2009 | TMC | ##1#R | 0001001 – 0132699 8000000 – K041367 | May 14, 2002 through August 19, 2009 | 602,654 |
| Toyota/ RAV4 | 2006- 2010 | TMC TMMC | ####V | 5000001 – 5098459 6000001 – D039942 W001048 – W082387 | July 28, 2005 through September 8, 2010 | 760,590 |
| Lexus/ LX570 | 2008- 2011 | TMC | HY### | TBD | TBD | TBD |

We will provide additional information as it becomes available. Should you have any questions, please contact the undersigned.

Sincerely,



Vinnie Venugopal
General Manager
Toyota Motor Engineering & Manufacturing
North America, Inc.