
From: StevePayne@Freightliner.com
Sent: Wednesday, November 19, 2003 11:31 AM
To:
Subject: RE: 03V-227 - Vehicle models

The work instructions have been sent to dealers and notifications have been sent to customers. We will submit a supplemental report this week including a list of the affected models determined from the population for the notifications.

The complete list of affected models is
Freightliner: Coronado, Columbia, FLD, FLD SD, Classic, Classic XL, Argosy, Business Class M2, FL112, Business Class, Century ST
Western Star: 4900FA
Sterling: AT9500

Thank you again for your patience,
Steve

-----Original Message-----

From: Taylor, Judy <NHTSA> [mailto:Judy.Taylor@nhtsa.dot.gov]
Sent: Friday, June 20, 2003 3:21 AM
To: StevePayne@Freightliner.com
Subject: RE: 03V-227 - Vehicle models

Thanks.

-----Original Message-----

From: StevePayne@Freightliner.com
Sent: Thursday, June 19, 2003 5:18 PM
To: Judy Taylor
Cc: TimothyBlubaugh@Freightliner.com
Subject: 03V-227 - Vehicle models

Unfortunately, we put these fifthwheels on several tractor models and won't know exactly which ones until we run the reports to send the customer and dealer notifications. Most components used by the custom truck manufacturers have fairly generic application on several models but are not used on every truck. Unlike a bracket that is only used on specific model car, we have a lot of parts that fit anything. Best I can tell you now is that they were used on certain truck-tractors, but not any straight trucks.

Any information on the vehicle models that we could send now would be incomplete or inaccurate. We would not want to provide information that includes models that are not affected or miss some that are.

We will supply more specific model information and an accurate count of the population on a supplemental report with the copies of the owner notifications.

Please call me if you need more information
Thanks, Steve
503/745-8063