



INTERNATIONAL TRUCK AND ENGINE CORPORATION
 4101 WINFIELD ROAD, WARRENVILLE, IL 60555

03V-083

TRUCK GROUP

RECALL REMINDER FOR SAFETY RECALL 03503

February 2004

Dear International Truck Customer:

This Recall Reminder is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. International has decided that a defect related to motor vehicle safety exists in the driver's seat on your vehicle. The vehicles involved are 4700 models built from 12/13/94 through 9/4/96 with one of the following Bostrom driver's seat models: 910, 910SC, or 914 and with International's parking brake code 04036.

The vehicle identified on the attached card fits this description. *Our records show that you own this vehicle and were sent an Initial Safety Recall Notification in March of 2003.* Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

If someone outside the cab adjusts/slides the driver's seat to its most forward position, with the parking brake set, the seat may contact and release the parking brake lever.

If the parking brake is accidentally released, the vehicle could move unexpectedly and the vehicle could be involved in an accident, possibly resulting in property damage, personal injury, or death.

In the event you no longer own the vehicle described on the card, please complete the card, fill in the new customer name and address if known, and return it to us. This information will allow us to update our records so that we can contact the current owner and you will not be contacted again regarding this recall.

Please contact your local International dealer to schedule an appointment and have the service procedure completed. Be prepared to read your vehicle identification number from your attached card, when you call to schedule an appointment. The remedy is to install a seat stop kit on the driver's seat. The repair will be made without charge to you and will require approximately 30 minutes of repair time.

ALL VEHICLES IN THIS SAFETY RECALL MUST BE CORRECTED.

If the vehicle will not or cannot be corrected, please mark on the attached card the box which best describes why the vehicle will not be repaired, and return the postage-prepaid card to us.

WE URGE YOUR PROMPT ATTENTION TO THE CORRECTION OF THIS SAFETY DEFECT AND APOLOGIZE FOR ANY INCONVENIENCE THIS MAY CAUSE YOU.

INTERNATIONAL TRUCK AND ENGINE CORPORATION

**AUTHORIZATION FOR RECALL
 SERVICE REMINDER**

Model Name	Vehicle Identification Number (VIN)	TSL	Dealer Code	Campaign #

Please check only one (1) of the following:

- 1 Vehicle inspected - no correction necessary.
- 2 Vehicle corrections completed.
- 3 I do not own this vehicle any more.
 (Please complete the NEW OWNER INFORMATION block)
- 4 Service Not Desired. Reason: _____
- 5 Vehicle Scrapped (junked). Will not return to public streets.
- 6 Vehicle Stolen (return status unknown).
- 7 Vehicle exported from U.S. to another country.
 (Please complete the NEW OWNER INFORMATION block)



New Owner Information

Name _____
 Street _____
 City _____ State _____ Zip _____