



SUBJECT:		No:	SR-04-003
TIRE AND LOADING INFORMATION LABEL — SAFETY RECALL CAMPAIGN		DATE:	April, 2004
		MODEL:	See below
CIRCULATE TO:	<input checked="" type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input checked="" type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input checked="" type="checkbox"/> WARRANTY PROCESSOR	<input checked="" type="checkbox"/> SALES MANAGER

PURPOSE

The Tire and Loading Information Label on affected vehicles states the incorrect vehicle capacity weight. If a customer wishes to have the dealer install the label, follow the instructions in this bulletin.

AFFECTED VEHICLES

2004 Montero and Montero Sport vehicles produced before 1/29/04

CUSTOMER NOTIFICATION


A letter will be sent to all owners of affected vehicles, instructing them to affix the corrected label to the vehicle. If they do not wish to affix the label themselves, they can bring it to a Mitsubishi Motors dealer to have it installed. A sample copy of a customer notification letter appears later in this bulletin.

REQUIRED OPERATIONS

Affected new or used inventory vehicles must have the corrected label installed before the vehicle is sold. A list of affected VINs in your dealership's inventory is enclosed with this bulletin, along with the corrective labels. If a VIN on this list was recently sold, please contact the owner to bring their vehicle in for this label installation.

To install the new Tire and Loading Information label:

1. Remove the clear film from the original Tire and Loading Information label, located on the driver's side B pillar.



FILE UNDER:

Safety Recall Bulletins in the Dealer Service Information Binder

(2727)

2. Affix the provided new Tire and Loading Information label over the original label.

MONTERO SPORT				MONTERO			
 TIRE AND LOADING INFORMATION				 TIRE AND LOADING INFORMATION			
SEATING CAPACITY		TOTAL 3	FRONT 2	REAR 3		SEATING CAPACITY	
		TOTAL 7	1ST 2	2ND 3	3RD 2		
The combined weight of occupants and cargo should never exceed 380 kg or 850 lbs.				The combined weight of occupants and cargo should never exceed 495 kg or 1091 lbs.			
ORIGINAL TIRE SIZE		COLD TIRE INFLATION PRESSURE		ORIGINAL TIRE SIZE		COLD TIRE INFLATION PRESSURE	
P255/70R18		FRONT	180kPa, 26PSI	265/70R16		FRONT	200kPa, 29PSI
		REAR	180kPa, 26PSI			REAR	200kPa, 29PSI
PART NO. 7430A137 B				PART NO. 7430A128			

WARRANTY INFORMATION

No warranty claims should be submitted for this campaign.



AFFECTED VEHICLES:

MODELS: 2004 Montero
2004 Montero Sport

Date: April, 2004

RE: **IMPORTANT SAFETY RECALL NOTIFICATION: SR-04-003**

Dear Mitsubishi Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Reason For Notice: Mitsubishi Motor Sales of America, Inc. has determined that the Tire and Loading Information Label located on the driver's door sill states the incorrect vehicle capacity weight. Overloading can damage your vehicle, adversely affect vehicle performance, including handling and braking, cause tire failure, and result in an accident.



What You Should Do: A corrected Tire and Loading Information label is provided with this letter. Remove the clear film from the original Tire and Loading Information Label on the vehicle. Then remove the backing from the new label and affix it over the original label. If you do not wish to affix the new label yourself, bring the label to your Authorized Mitsubishi Motors Dealer to affix the label. There will be no charge for this service.

If you have any trouble with having the corrective Tire and Loading Information label installed, please inform us by calling:
Mitsubishi Customer Relations Department (888-MITSUBU-2804 (888-648-7820))
Hours: Monday - Saturday 7 a.m. to 10 p.m. (Central Standard Time)

If after contacting Mitsubishi Customer Relations, you still have a problem having the corrective label installed promptly and without charge, write to the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street SW, Washington, D.C. 20590, or call the Auto Safety Hotline toll-free (866) 827-4238.

Notice to Lessors: If you are a lessor of five or more leased vehicles as of the date of this letter, you have an obligation under federal law, (49 CFR Part 577), to provide the lessee of the above referenced vehicle with a copy of this letter by first class mail within ten days of receipt. Further, you must maintain a record, which identifies the lessee to whom you sent a copy of this letter, the date you sent it, and the vehicle identification number (VIN) of the subject vehicle.

We appreciate your prompt attention to this matter. If you have any questions, please contact your Mitsubishi Motors Dealer.

Sincerely,

Chuck Halper
Director, Service and Product Support