


GROUP
CampaignMODEL
SportageNUMBER
017DATE
August 2000

Technical Service Bulletin

SUBJECT:**Owner Notification Campaign - Sportage Owners Manual**

This bulletin provides information related to a owner notification on 2000 model year Sportage to correct an error in the Owners Manual. The jump starting diagram in the Owners Manual is incorrect. If the diagram were followed, spark/arcing could cause the battery to explode causing potential serious injury to bystanders.



To correct this error, Kia is sending a letter and correction sticker to all 2000 model year Sportage owners asking them to apply a correction sticker to page 6-5 in their Owners Manual.

For your in-stock 2000 model year Sportages and owners requesting that a dealer install their correction sticker, refer to correction sticker application on next page.

*** NOTICE**


There is no charge to the customer for this procedure. Under applicable law, you may not sell or otherwise deliver any 2000 model year Sportage until the Owners Manual has been corrected, pursuant to the procedure set forth in this bulletin.

File Under: Campaign

Circulate To: General Manager Service Manager Parts Manager
 Service Advisor(s) Technician(s) Body Shop Manager

SUBJECT:**Owner Notification Campaign - Sportage Owners Manual****CORRECTION STICKER APPLICATION**

1. Remove Owners Manual from Information packet in glove box.
2. Open Owners Manual to page 6-5.
3. Apply supplied sticker with revised battery jumper connections in location shown below.



4000000000
6-5

AFFECTED PRODUCTION RANGE:

All 2000 model year Sportage.

PART NUMBER INFORMATION:

Description	P/N
Correction Sticker	UP010 PS 013 LB

WARRANTY CLAIM INFORMATION:

Repair Description	Claim Type	Condition Code	Cause Code	Labor OP Code	Time	Causal P/N	Related Parts	Quantity
Apply Owners Manual Sticker	R	N99	C99		0.2	UP000 PS 013	UP010 PS 013 LB	0

August XX, 2000

Attention: All Kia Service Managers

Kia Motors Corporation, in cooperation with the National Highway Traffic Safety Administration, is conducting a voluntary Recall Campaign on 2000 Sportage models to apply a correction sticker in the Owners Manual to correct an error in the jump starting procedure.

Kia will send a correction sticker to all 2000 Sportage owners asking them to apply the sticker to the affected page in their Owners Manual.

Enclosed is a Technical Service Bulletin that provides the following information:

- Correction Sticker Application Procedure
- Affected VIN Production Range
- Parts Information
- Warranty Claim Information

Also enclosed is a copy of the owner notification letter, a list of your in-stock vehicles, and a sufficient number of correction stickers for your inventory and customers who may have misplaced their sticker. Please start performing the corrections to your affected in-stock 2000 MY Sportage Owners Manuals immediately.

Please make certain the appropriate personnel in your dealership are familiar with the details of this recall to ensure proper responses to customer inquiries.

Your prompt attention in completing this recall is appreciated. If you have any questions, please contact your Kia District Parts/Service Manager.

Sincerely,

Lee Sawyer
Senior Vice President,
Fixed Operations

Enclosures