

MAY 17 2004

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 04E-036 by the
National Highway Traffic Safety Administration

Part 573 Report Date: **May 11, 2004**

Date Faxed: **May 17, 2004**

MANUFACTURER: **EMC**

MANUFACTURER CONTACT: **JON ROSS**

FAX: **225-924-5556**

SUBJECT: 583 EMC AEVIT. THE EMC ACCELERATOR CABLE ANCHORAGE MAY NOT HAVE BEEN FULLY SECURED POSSIBLY ALLOWING THE ACCELERATOR CABLE TO BECOME DISCONNECTED FROM THE ACCELERATOR PEDAL. IF THE CABLE BECAME DISCONNECTED WHILE THE VEHICLE IS IN MOTION, THE ENGINE SPEED WOULD RETURN TO IDLE WHERE IT WOULD REMAIN REGARDLESS OF THE OPERATOR'S THROTTLE INPUTS, POSSIBLY RESULTING IN A VEHICLE CRASH.

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to consumers.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin May 25, 2004. Therefore, EMC's first quarterly report will be due in the office on or before July 30, 2004.

If you have any questions, please call:

K.S.

Kelly Schuler, Safety Defect Analyst or George Person, Chief
at (202) 366-5227 or by FAX (202) 366-7882
Recall Management Division
kschuler@nhtsa.dot.gov
Faxed on 5/17/04